

TECHNICAL INFORMATION


Document: TI_T318_033
Date: 01/09/2020
Subject: Front flap adjustment plate

Reference:	Table	Item	Code
	03-A	16	2403055
	03-A	17	2403056

Accomplishment: Immediate

It is allowed to adjust the countersink of the hole for the UNI5933-M4 screw on p/n 2403055 and 2403056 in order to have a smoother installation of bolts' head.

Please refer to the drawing below as a reference for the countersink dimensions:



Please note that also the countersink on the flap could need to be adjusted accordingly.